

SHOPSMITH VARIABLE SPEED CHANGER CHART

Indicator Reading	Low Range R.P.M.	High Range R.P.M.
0	425	1850
1	555	2500
2	745	3300
3	960	4200
4	1225	5500
5	1600	6800

**All above speeds are only approximate and may vary
according to belt tension, or wear, or current voltage.**